

Oil Field Environmental Incident Summary

Incident: 20160207102411 **Date/Time of Notice:** 02/07/2016 10:24

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: CLEARWATER 200-06 SWD

Field Name: CLEAR WATER

Well File #: 90180

Date Incident: 2/6/2016

Time Incident: 14:15

Facility ID Number:

County: MOUNTRAIL

Twp: 157

Rng: 90

Sec: 6

Qtr:

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	8	Barrels	8	Barrels	8	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/18/2016

Clean Up Concluded: 2/6/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The liquids were removed by vac truck and the gauge will be replaced. If any further cleanup is done it will be included in the NDIC Follow-up Spill Report.

Wastes Disposal Location: The liquids were disposed of at SWD

Agencies Involved:

Updates

Date: 2/8/2016 ***Status:*** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained within diking according to the report. NDIC retains oversight.